## Republiced from the holdings of the National Archives Pacific Southwest Region

HOLMES & NARVER, INC. ENGINEERS

405742

R

## WEXLY INSPECTION REPORT

Bldg. or Sts. 1202 W.O.	3217	_ Site	Charlie-reef	
For We	ek onding _	11-14-53		
WORK UNDERTAKEN Interior wal re-steel. M wall forms b	lost of wall	electrical	openings. Placing conduits installe p.	g wall ed. Outside
MANPOWER AND EQUIPMENT				
CONCRETE LOG  Proviously Paured 46.5	• •			
Previously Poured 46.5  Poured this Report 00		,		e.
Total to date: 46.5		Total I	Istimated Required	220
REMARKS				
BEST COPY AVAILABLE	COLLECTION BOX No. 12	RY <u>PACIFIC S</u> ON <u>RG 326 A</u> 19624 (#608 ELMER GENER	ARCHIVES OUTHWEST REGION TOMIC ENERGY COMMI I A16334 326-65 VO. 14L JECT ENGINEERING FIL	170

DISTRIBUTION:
Resident Engineer
A.E.C. Resident Engineer
Historian
Accountant

/s/ .	Al Barabas	
Inspector.		