4	SECURITY INFORM	ENGINEERS-CONSTRUCTORS
TO;	D. L. NARVER, JR.	JOB. NO. 884 Am R. Kon
FROM:	C. L. EAST	RE: DISCREPANCIES BETWEEN DRAWINGS AND INSTRUMENTATION
		DATE: NOVEMBER 18, 1953

The following is a list of possible discrepancies, omissions, or oversights as observed between the "Instrumentation Chart" and the detail drawings as issued by the Engineering Division.

	Station Number	Instrumentation Chart Location	Detail Drawing Location	Remarks
	Eniwetok Atoll	ann air fair aige a fair aige a dhaille an gan air an		Hand the second s
- -	Eniwetok Atoll 1811.03 711 3328 1403.17 232.09 232.10 232.12 61 at 60 2231 2230 2231.01 232.08 Bikini Atoll	Not Shown Not Shown Not Shown	Lucy	Can't find on detail dwg. Can't find on detail dwg. - De/efect "" Can't find on detail dwg. e as 2231.01 Between Ruby & Sally
Same	2230	Sally	Ruby Pipeline	Between Ruby & Sally
	232.08	Not Shown		
	Bikini Atoll	• •	•	
DEPARTMENT OF ENERGY DECLASSIFICATION REVIEW SINGLEREVIEW AUTHORIZED ETC: DETERMINATION (CIRCLE MUMBER(S)) SINGLEREVIEW AUTHORIZED ETC: DECERMINATION (CIRCLE MUMBER(S)) TERVIEWENVEN REVIEWENVEN MARE: 7, 28, 94 DATE: 7, 28, 94 DATE: 7, 28, 94 DATE: 7, 28, 94 DATE: 7, 28, 94 S. CLASSIFIED INFO BRACKTED	2220 2221.02 51 + 50 122.16 122.17 162.02 312.01 thru $05$ 1120.01 1354 1355 1356 232.03 1811.01 1402 1403.15 1403.16 10 30 40 90	Tare Tare Tare Detrive PEQUIRES Uncle Zebra USER To SUPPLY STA Able Able Able Unnamed	Uncle CIVIL 22020 Uncle II II $J = J = \int_{a}^{b} \int_{a$	Will Electrical System dwg. be sufficient? Can't find on detail dwg. Can't find on detail dwg.
••••••••••••••••••••••••••••••••••••••		<b>.</b>	BOX No.	199624 (#608) A16334 326-65Voi 70 SuRVEYS
			FOLDER -	AUGUST 1, 1953 ON

## Reproduced trop the udlings of the National Archives HOLMES SIMARVER, In Region

ENGINEERS-CONSTRUCTORS

ROM:	C. L. EAST	PE DISCRE	PANCIES BETWEEN DR	AWINGS AND INSTRUMENTATION
KUM:		RC1		CHART
	PAGE TWO		DATE: NO	VEMBER 18, 1953
	Station Number	Instrumentation Chart Location	Detail Drawing Location	Remarks
	Bikini Atoll			
	11	Lagoon at 10		Can't find on detail dwg.
	31	Lagoon at 30		Can't find on detail dwg.
	41	Lagoon at da		Can't find on detail dwg.
	91 山3.01	Lagoon at 90		Can't find on detail dwg.
	thru oly	Lagoon	Tarel (viers reques	ted an know he stored
	1/4.01		The true	fit needed. Actual location not know
	thru .16	Lagoon	Tare	The needed, Heren not were
	<b>11</b> 11	Lagoon at 30		Can't find on detail dwg.
	1112	Lagoon at 10		Can't find on detail dwg.
	1113	Lagoon at 40		Can't find on detail dwg.
	<b>11</b> 1/ <sub>4</sub>	Lagoon at 90		Can't find on detail dwg.
	1216	Lagoon at 30	••• ••	Can't find on detail dwg.
	162.01	Nan	ECE 4 3387- NA-1	Is electrical system layout
	<b>71</b> 0	Nan North end Non	CIVIL 2205 NAI	A)Can't find on detail dwg.
	120.12	Not Shown	Roger Civic	2202 0B1 wh 2229 SU 17
	1350.01		··· 0··· /	2224 50 11
	thru .12	Unnamed very close to 20	Charlie	Should this be Reef (Charl:
	1 <b>1</b> 10	Unnamed at 20		Can't find on detail dwg.

The exact location of all work affects our estimates considerably. It is therefore requested that the above discrepancies be cleared up as soon as possible.

CLE:GAK:rds

cc: Manager, Construction-Operations Chief of Construction-Operations Estimating Files Central Files

TILSTINGTED